X30 Apollo | System



www.bourgault.com



X30 Apollo System Detecting ECU's






For the X30 Apollo system each ECU must be "Detected" before the X30 will recognize it.

This means that each tank will have to have the following procedure done for X30 to run the tank.

If there is no ECU ISO Name a Detect must be performed.






Unplug all COMMS connectors in all of the ECU's except for the one to be detected.

COMMS Unplugged CM-40 slave and CM-24

COMMS Plugged in CM-40 Master





Go to Implement/ ECU/ Add/Replace ECU

Press tab under Status corresponding to the ECU to be detected,


Select Replace CM-40

Press the Check mark






Follow the wizard instructions, when conditions met press the arrow at lower right.






Once the ECU is detected and arrow turns yellow press to advance.







Once the ECU is detected Name and Type of ECU will be displayed. Press green check mark to advance.





The system should upload/ Configure/Synchronize

If this does not start within a couple of minutes it may be necessary to unplug the ISO plug at the back of the tractor and plug it back in.








When the upload is complete, the ECU ISO Name will be listed as well as the Firmware version currently on ECU.

If there is only one ECU on tank you are done.

If there is more than one ECU follow the appropriate procedure for additional ECU's






Plug the COMMS plug into the second CM-40 (slave)

CM-24 (I/O ECU) not detected

CM-40 (Master ECU) previously detected.






In settings go to
Implement/
ECU/
Add/Replace ECU

Press tab under status for the second CM-40 named CM-40 1, select replace and then press the check mark





Make sure the second CM-40 is plugged in before pressing the arrow to advance.






ECU is being detected





When detect is complete Name and Type are displayed. Name for second CM-40 that is detected is Apollo CM-40 1

Press check mark to advance.





The system should upload/ Configure/Synchronize When complete ISO Name and Firmware version will be displayed.

If this does not start within a couple of minutes it may be necessary to unplug the ISO plug at the back of the tractor and plug it back in.






Plug COMMS connector into CM-24

CM-40 (Master ECU) slave (previously detected)

CM-40 (Master ECU) (previously detected)





In settings go to
Implement/
ECU/
Add/Replace ECU

Press tab under Status for Apollo EM-24 1, select Replace, press check mark.





Make sure EM-24 1 is connected.

Press the arrow to advace.






Attempting to detect ECU





ECU has been detected Name and Type displayed

Press check mark to advance.





The system should upload/ Configure/Synchronize

If this does not start within a couple of minutes it may be necessary to unplug the ISO plug at the back of the tractor and plug it back in.





When Synchronizing is complete ISO Name and Firmware version will be displayed for Apollo EM-24 1

If there is only one CM-24 on the machine you are finished.

If there is both ASC and Blockage there will be a second CM-24. Repeat the procedure for CM-24 for the second ECU.

