

## **Gleaner Feeder Drive Snubber**

(Fits all Gleaner Rotary Combines, 1993-UP,  
with constant speed header drives)

When using an AGCO auger style header (pick-up or straight cut) with the radial pin style slip clutch, the severe ratcheting action of the slip clutch when plugged often causes the LH feeder drive idler to bounce violently and break a belt or cause one of the belts to fall off the pulleys.

Our kit is easily installed with only a drill and hand tools, and helps greatly reduce this problem. Watch the following video to show how a combine reacts when the header auger is plugged and no snubber kit is installed. ([video link](#)).

