

Chart 1A

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 1B

(for rates below 50lb/ac use a minimum fan speed of 30000 RPM)




Chart 1C

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 1D

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 1E

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 1F

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)

