

Chart 10A

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 10B

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 10C

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 10D

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 10E

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 10F

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)

