



# Chart 2A

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)



**Chart 2B**


(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)



# Chart 2C


(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)

**Product: Chickpea / Pea**  
**Machine: 8 Port 7" Trailing System**  
**Fan: High Speed**




### Chart 2D

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)



# Chart 2E

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)



# Chart 2F

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)

