

Chart 3A

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 3B

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 3C

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 3D

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 3E

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 3F

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)

