

Chart 4A

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 4B

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 4C

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)

Product: Chickpea / Pea
Machine: 10 Port 7" Trailing System
Fan: High Speed




Chart 4D

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 4E

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)

Product: Barley
Machine: 10 Port 7" Trailing System
Fan: High Speed

Chart shows optimum Minimum Fan RPM required. Deviations from this may be required due to operating conditions. (Seed density, treatments, humidity, etc.)




Chart 4F

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)

Product: Oat
Machine: 10 Port 7" Trailing System
Fan: High Speed

Chart shows optimum Minimum Fan RPM required. Deviations from this may be required due to operating conditions. (Seed density, treatments, humidity, etc.)

