

Chart 8A

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 8B

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 8C

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)

Product: Chickpea / Pea
Machine: 8 Port 7" Leading System
Fan: High Speed




Chart 8D

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)




Chart 8E

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)

Product: Barley
Machine: 8 Port 7" Leading System
Fan: High Speed




Chart 8F

(for rates below 50lb/ac use a minimum fan speed of 3000 rpm)

