

Chart 9A

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)

Product: Wheat
Machine: 6 Port c/w 6" Hybrid S-Pipe
Tank: Leading
Fan: High Speed




Chart 9B

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 9C

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 9D

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 9E

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)




Chart 9F

(for rates below 50lb/ac use a minimum fan speed of 3000 RPM)

