

7000 A/S Minimum Fan Speed Chart Legend

Drill Configuration			Chart Required			
			Section A (Trailing Units)		Section B (Leading Units)	
Model	Spacing	Number of Ports	High Speed Fan	High Cap Fan	High Speed Fan	High Cap Fan
3320-50	10	6	3A ~ 3F		7A ~ 7F	
	12	6	3A ~ 3F		7A ~ 7F	
3320-60	10	6	1A ~ 1F		9A ~ 9F	
	12	6	1A ~ 1F		9A ~ 9F	
3320-66	10	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	12	6	1A ~ 1F		9A ~ 9F	
3320-76	10	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	12	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
3320-80	10	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	12	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
3320-86	10	10	4A ~ 4F	6A ~ 6F		
	12	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
3720-50	7.5	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	10	6	3A ~ 3F		7A ~ 7F	
	12	6	3A ~ 3F		7A ~ 7F	
3720-60	7.5	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	10	6	1A ~ 1F		9A ~ 9F	
	12	6	1A ~ 1F		9A ~ 9F	
3720-70	10	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	12	6	1A ~ 1F		9A ~ 9F	

Example: For a 3320-76 @10" spacing, Trailing Tank with High Capacity fan - use Min Fan Chart 5A ~ 5F

7000 A/S Minimum Fan Speed Chart Legend

Drill Configuration			Chart Required			
			Section A (Trailing Units)		Section B (Leading Units)	
Model	Spacing	Number of Ports	High Speed Fan	High Cap Fan	High Speed Fan	High Cap Fan
3320-50	10	6	3A ~ 3F		7A ~ 7F	
	12	6	3A ~ 3F		7A ~ 7F	
3320-60	10	6	1A ~ 1F		9A ~ 9F	
	12	6	1A ~ 1F		9A ~ 9F	
3320-66	10	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	12	6	1A ~ 1F		9A ~ 9F	
3320-76	10	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	12	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
3320-80	10	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	12	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
3320-86	10	10	4A ~ 4F	6A ~ 6F		
	12	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
3720-50	7.5	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	10	6	3A ~ 3F		7A ~ 7F	
	12	6	3A ~ 3F		7A ~ 7F	
3720-60	7.5	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	10	6	1A ~ 1F		9A ~ 9F	
	12	6	1A ~ 1F		9A ~ 9F	
3720-70	10	8	2A ~ 2F	5A ~ 5F	8A ~ 8F	10A ~ 10F
	12	6	1A ~ 1F		9A ~ 9F	